




Integrated Power Monitor

NOTE: Traces connect only at pad centers. Crossings do not touch.

Tape a

Tape b



Mag/Piezo Grounding de-selects

Mono/Stereo Push Switch

Output (ring) (Piezo) Stereo

Output (tip) (Mag) Stereo